

● NOT RECOMMENDED

Lexus RX 400h

196,808 km VIN / Chassis: DEMO-XXXXXX-0000

CLIENT

Client

INSPECTION

Inspection date: **06.05.2026**

Location: **Fribourg, FR**

DEMO-2026-001

AREA ASSESSMENT



Exterior



Structure



Interior



Mechanics



Road Test

ESTIMATED COSTS

Immediate repairs	CHF 5,500
Short term (3–6 months)	CHF 1,700
Next maintenance	CHF 620
Total estimate	CHF 7,820

CONCLUSION

The engine and hybrid drivetrain appear to function well at first glance. The steering has a problem, likely the rack and pinion. Several interior systems are not functioning: passenger-side and rear window regulators, rear seatbelts. Rear parking sensors are non-functional, though the camera works. The main issue is underbody rust — passing the already-expired MFK roadworthiness inspection will be very difficult. Due to the condition of the underbody, I do not recommend this vehicle.

Exterior

ELEMENT	STATE	OBSERVATIONS
Bodywork	⚠ Attention	
Paint / touch-ups	✓ OK	
Panel alignment	⚠ Attention	
Oxidation / rust	⚠ Attention	
Windows & lights	✓ OK	
Tyres	⚠ Attention	
Wheels	⚠ Attention	
Underbody	✖ Problem	

Multiple scratches visible. Left front wing bent/misaligned. Fuel flap deformed. Wheels scratched. Visible rust traces on underbody.

Structure

ELEMENT	STATE	OBSERVATIONS
Structural accident signs	✓ OK	
Sill panels / welds	⚠ Attention	
Pillars / strut towers	⚠ Attention	
Boot	✓ OK	
Front subframe	⚠ Attention	

No structural accident signs. Structural elements showing advanced rust.

Interior

ELEMENT	STATE	OBSERVATIONS
Wear consistent with mileage	✓ OK	
Air conditioning	✓ OK	
Multimedia	✓ OK	
Windows / central locking	✗ Problem	
Warning lights / lighting	✓ OK	
Upholstery / moisture / odours	✓ OK	

Interior heavily worn but consistent with age and mileage. Passenger-side and rear window regulators non-functional. Rear seatbelts non-functional.

Mechanics

ELEMENT	STATE	OBSERVATIONS
Cold start	✓ OK	
Idle	✓ OK	
Abnormal noises	✓ OK	
Leaks	✓ OK	
Belts / hoses	✓ OK	
Battery	✗ Problem	
OBD Diagnostic	✓ OK	
Brakes	⚠ Attention	
Suspension	⚠ Attention	
Power steering	⚠ Attention	

Engine oil at minimum level, no leaks detected. Power steering requires increased effort — inspection recommended.

Road Test

ELEMENT	STATE	OBSERVATIONS
Gearbox / clutch	✓ OK	
Acceleration	✓ OK	
Vibrations	✓ OK	
Steering	⚠ Attention	
Braking	✓ OK	
Road noise	✓ OK	

Power steering requires increased effort — inspection recommended.

DOCUMENTATION	
MFK / Inspection date 05/2024	MFK valid until Expired
Service book Not available	Invoices No
No. of owners —	Modifications No modifications

INSPECTOR'S DECLARATION

This inspection is a non-destructive visual and functional assessment. It does not replace an official diagnosis. The inspector cannot be held responsible for hidden defects or defects not visible at the time of inspection.

INSPECTOR

Autoinspect24
contact@autoinspect24.ch
autoinspect24.ch

Generated on 01.06.2026

CLIENT SIGNATURE

Client