

Autoinspect24 Recommendation

● Recommended

1 · VEHICLE AND CLIENT DATA

Client	Jean-Pierre Müller
Make / Model	Volkswagen Golf · 1.6 TDI Comfortline
VIN / Chassis	WVWZZZ1JZ3W386752
Mileage	87'500 km
Inspection Date	10/04/2026
City / Canton	Lausanne, VD

2 · DOCUMENTATION (SWITZERLAND)

MFK — Last / Valid until	03/2024 / 03/2026
Service booklet	Yes — complete
Invoices available	Yes
Number of owners	1
Non-approved modifications	No — no modifications

OBSERVATIONS: Complete history, all stamps present.

3 · EXTERIOR

Body (dents / scratches)	● OK
Paint / repainted areas	● Attention
Panel alignment	● OK
Rust / corrosion	● OK
Windows and headlights	● OK
Tires (mm and wear)	● Attention
Rims	● OK
Undercarriage visible (if accessible)	● OK

OBSERVATIONS: Touch-up paint visible on rear left fender. Rear tires at the limit (~2mm).

4 · STRUCTURE

Signs of structural accident damage	● OK
Chassis rails / welds	● OK
Pillars / strut towers	● OK
Boot (floor and sides)	● OK
Front supports	● OK

5 - INTERIOR

Wear consistent with mileage	● OK
Air conditioning (AC / heating)	● OK
Multimedia / screen / sound	● OK
Power windows / central locking	● OK
Lighting / dashboard warning lights	● Attention
Upholstery / humidity / odors	● OK

6 - MECHANICS AND DIAGNOSTICS

Cold start	● OK
Idle	● OK
Abnormal noises (engine / chain / timing)	● OK
Leaks (oil / coolant / other)	● OK
Condition of belts / visible hoses	● Attention
Battery (if measured)	● OK
Brakes (visual)	● OK
Suspension (visual / noises)	● OK
Power steering	● OK

OBD Diagnostic: ● No fault codes

OBSERVATIONS: Auxiliary belt with slight wear. Replacement recommended at next service.

7 - ROAD TEST

Gearbox / clutch	● OK
Acceleration and response	● OK
Vibrations	● OK
Steering (alignment / pulling)	● OK
Braking	● OK
Driving noises	● OK

8 · VEHICLE PHOTOS

[Photos are available in the original report]

9 · EXECUTIVE SUMMARY

Final Recommendation

● **Recommended**

Overall assessment by area:

Exterior	● Attention
Structure	● OK
Interior	● OK
Mechanics and diagnostics	● OK
Road test	● OK

Professional conclusion:

Vehicle in good overall condition, consistent with the declared mileage.
Touch-up paint detected on the rear left fender with no structural damage.
Rear tires to be replaced in the coming months.
We recommend negotiating the ~CHF 550 in upcoming maintenance costs.

Estimated costs (CHF):

Immediate repairs (safety / MFK)	0 CHF
Short-term repairs (0–6 months)	200 CHF
Next service (maintenance / consumables)	350 CHF

ESTIMATED TOTAL

550 CHF

Inspector

Rui Dias - Autoinspect24

Tel. +41 79 000 00 00
rui@autoinspect24.ch

Generated on: 11/04/2026 19:10
autoinspect24.ch